

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/20/20 Time: 9:19 am Weather: Cloudy 49°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

Approximately ~ 10 feet of 2nd GEO Tube exposed.



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Walked along the template and the ramps.



Approximately 4.5 cubic feet of debris such as bricks, concrete, PVC and electric wire were collected from delivery area during template grading.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/21/20 Time: 8:16 am Weather: Sunny 35°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

GEO tubes were covered during 04/20/2020 maintenance.



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.



10gl. bricks, small amount of wire, few small concrete blocks and landscaping felt were collected during template grading at the delivery area

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/22/20 Time: 8:06 am Weather: Sunny 40°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

GEO tubes were covered during 04/20/2020 maintenance.



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.



~ 5gl. bricks, small amount of wire and 2 concrete blocks were collected during template grading at the delivery area.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/23/20 Time: 7:36 am Weather: Sunny 41°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

GEO tubes were covered during 04/20/2020 maintenance.



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.



~ 5gl. bricks, small rope, 2 stainless still metal and few concrete blocks were collected during template grading at the delivery area.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/24/20 Time: 9:16 am Weather: Rainy 46°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

No exposed GEO tubes.



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.