

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/27/20 Time: 9:17 am Weather: Rain 46°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

GEO tubes completely covered



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/28/20 Time: 7:26 am Weather: Rainy 39°F

General Site Conditions:

No access to beach due to active storm

Length of Exposed Geotube:

Tube exposed significantly during last night's storm ~ 650'



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/29/20 Time: 7:56 am Weather: Sunny 48°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

~600' of GEO Tube exposed



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 04/30/20 Time: 7:17 am Weather: Cloudy 45°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

~570' of GEO Tube exposed



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 05/01/20 Time: 8:19 am Weather: Rainy 51°F

General Site Conditions:

Site was in good condition.

Length of Exposed Geotube:

~500' of GEO Tube exposed



Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.