

2020

# SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 05/04/20 Time: 12:29 pm

Weather: Sunny 54°F

## General Site Conditions:

Site was in good condition.

## Length of Exposed Geotube:

~560 GEO Tube exposed



## Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

# SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 05/05/20 Time: 2:59 pm Weather: Cloudy 49°F

## General Site Conditions:

Site was in good condition.

## Length of Exposed Geotube:

~560 GEO Tube exposed



## Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

# SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 05/06/20 Time: 8:29 am Weather: Cloudy 65°F

## General Site Conditions:

Site was in good condition.

## Length of Exposed Geotube:

~560 GEO Tube exposed



## Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.

2020

# SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 05/07/20 Time: 8:18 am Weather: Cloudy 45°F

## General Site Conditions:

Site was in good condition.

## Length of Exposed Geotube:

~560 GEO Tube exposed



## Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.





~ 1gl. small bricks, one red tape and few concrete blocks were collected during template grading at the delivery area.

2020

# SBPF Site Inspection Report/Log

Inspector: Ali Tepsurkayev

Date: 05/08/20 Time: 6:59 pm Weather: Sunny 53°F

## General Site Conditions:

Site was in good condition.

## Length of Exposed Geotube:

No exposed GEO tubes. Covered during 05/07/2020 template grading.



## Type & Quantity of Debris Removed/Action Taken:

Fully inspected the structure from North to South. Drove and walked along the template and the ramps.

No debris was collected during this inspection.