

INSPECTION WORKSHEET (IHLTH-019219-2022)

Town of Nantucket
508-228-7200

Case Number:		Case Module:	NONE
Inspection Date:	Mon Sep 19, 2022	Inspection Status:	Pass
Inspector:	Hedden, John D.	Inspection Type:	HLTH - Housing Complaint

Job Address:	10 OCEAN AV Nantucket, MA, 02554	Parcel Number:	73.2.4 15
---------------------	-------------------------------------	-----------------------	-----------

Contact Type	Company Name	Name
Property Owner	DEBENEDICTIS DANIELLE TR	

Checklist Item	Status
HLTH - General Comments - General Comments	Passed

Sewage spill has been neutralized, the top soil has been removed and replaced with clean dirt.


Hedden, John D.